FOURTH AVENUE GAMBELL, LLC
EXHIBIT RR



# ENVIRONMENTAL ASSESSMENT

Anchorage, Alaska

Final Report

THE FOURTH AVENUE GAMBELL ANCHORAGE, ALASKA

EnviroAmerica, Incorporated
Anchorage, Alaska

January 29, 1993

FOURTH AVENUE GAMBELL, LLC EXHIBIT RR

# ENVIRONMENTAL ASSESSMENT FOR

THE FOURTH AVENUE GAMBELL

ВΥ

ENVIROAMERICA, INCORPORATED

CONTRACT NUMBER: 1993-1

PREPARED BY: ENVIROAMERICA, INC. ANCHORAGE, ALASKA

PREPARED FOR: THE FOURTH AVENUE GAMBELL ANCHORAGE, ALASKA

January 29, 1993

# ENVIRONMENTAL ASSESSMENT TITLE PAGE

Document Title: ENVIRONMENTAL ASSESSMENT

Site Name: Block 26A - 4th and Gambell

Site Location: Anchorage, Alaska

Contract Number: 1993-1

Plan Coverage: This plan covers a field visual

survey and records search under a contract awarded by The Fourth Avenue Gambell. These services are provided by EnviroAmerica, Inc., as Prime

Contractor for the site survey indicated above and are described within the survey.

Organization Title: The Fourth Avenue Gambell

Address: 1343 G Street
Anchorage, Alaska 99501

•

Prime Contractor: EnviroAmerica, Inc.

Address: 3000 C Street Suite 101
Anchorage, Alaska 99503
(907) 563-0000

Quality Assurance Manager: Richard Glessel PE Telephone: (907) 563-0000

Project Manager: William de Schweinitz
Telephone: (907) 563-0000

sc or Bates 176

Concurrences:	
Name: Title:	William de Schweinitz Project Manager EnviroAmerica, Incorporated
Signature:	Date:
Name: Title:	William de Schweinitz President EnviroAmerica, Incorporated
Signature:	Date:
Approval for	The Fourth Avenue Gambell
Name: Title:	Paul Maney General Partner
Signature:	_ Date:

## Table of Contents

	Title ! Table	r Page	,
1.0	1.1 F	PROGRAM ORGANIZATION	l
2.0 5	2.1 2.2 2.3	PHYSICAL DESCRIPTION	2 2 3 3 4
3.0	3.1 3.2 3.3 3.4	RECORDS DATA SOURCES EVALUATED PUBLIC RECORDS REVIEW MAPS AERIAL PHOTOGRAPHS OTHER DATA SOURCES	.5 .5 .5
4.0	4.1 4.2 4.3	LATORY AGENCY LISTINGS	6. 6. 7.
5.0	SITE	HISTORY	8
6.0	DISC	USSION	1
A		און וויז וייי	44

# Appendices

Appendix A	Data Sources	14
Appendix B	State of Alaska List of Contaminated Sites	16
Appendix C	EA Data Collection Form.	32

## List Of Acronyms

ADEC Alaska Department of Environmental Conservation

ARAR Applicable or Relevant and Appropriate Requirements

CERCLA Comprehensive Environmental Response Compensation &

Liability Act

CERCLIS Comprehensive Environmental Response Compensation &

Liability Information System

DOT Department of Transportation

LUST Leaking Underground Storage Tank

EA Environmental Assessment

PCB Poly-chlorinated biphenyl

POL Petroleum, Oil, Lubricants

QA Quality Assurance

QC Quality Control

RCRA Resource Conservation and Recovery Act of 1976

SARA Superfund Amendments and Reauthorization Act of 1986

#### 1.0 INTRODUCTION

The Fourth Avenue Gambell has requested that services be provided by EnviroAmerica, Inc., to prepare and implement project plans for an Environmental Assessment of Lots 8A, 9, 10, 11, and 12 of Block 26-A, herein referred to as Block 26-A, in Anchorage, Alaska. The implementation of this Environmental Assessment has been performed under Contract Purchase Order No.: 1993-1

#### 1.1 PROGRAM TERMINOLOGY

The Fourth Avenue Gambell and EnviroAmerica have adopted terminology used by the U.S. Environmental Protection Agency (EPA) pursuant to the Superfund Amendments and Reauthorization Act (SARA) of 1986 in the preparation of this environmental assessment.

#### 1.2 OBJECTIVE AND SCOPE

This environmental assessment was undertaken to collect visual data and to conduct a record search to characterize site conditions of Block 26-A for The Fourth Avenue Gambell. Under this environmental assessment, EnviroAmerica, Inc. has performed a site visual inspection and a records search of Lots 8A, 9, 10, 11 and 12 of Block 26-A.

Complete site characterization studies including any soil or UST sampling, lithology studies, soil borings, geological or hydrological studies, or a land survey have not been conducted as a part of this environmental assessment.

1.

#### 2.0 SITE DESCRIPTION

#### 2.1 PHYSICAL DESCRIPTION

#### 2.1.1 Physiography

Block 26-A is located in downtown Anchorage, Alaska and occupies approximately 40,000 square feet. The site is located at the corner of East 4th Avenue and Gambell Street and is bordered on the west by Gambell Street, to the north by an alley adjacent to Lots 1, 2, 3, 4, 5 and 6 of Block 26-A, to the East by Hyder Street and to the south by East 4th Avenue. It is situated at approximately 61° 67' north latitude and 149° 46' west longitude. Anchorage is located between Turnagain Arm and Knik Arm at the edge of the Cook Inlet basin and is bordered to the east by the Chugach Mountains which rise abruptly to elevations of more than 3,500 feet above sea level. The mountain front declines in elevation from about 1,000 feet through a series of ridges and isolated hills to a lowland which averages about 80 feet above sea level that extends from the city of Anchorage southward to Turnagain Arm.

#### 2.1.2 Geology

The Anchorage plain is a large alluvial fan that rises gently north-eastward to an elevation of 500 feet. North of the Anchorage plain hummocky topography rises to heights of more than 300 feet and the entire lowland is separated from the sea by steep bluffs that range from less than 60 to more than 300 feet high. Only in relatively narrow valleys along the principal streams does the land approach sea level with a gentle gradient. The lower parts of these valleys are incised beneath the general lowland surface and separated from it by steep valley walls comparable to the sea bluffs.

Relatively hard but intensely fractured metamorphic rocks constitute the bedrock in the mountains and in isolated patches west of the mountain front. The lowland is underlaid by a wedge of surficial deposits that thickens from zero at the mountain front to at least 800 feet near Point Woronzof. Relatively soft sedimentary rocks underlie the surficial deposits but were not observed at the surface within the Ship Creek area.

Most of the surficial materials were deposited during the last of several glaciations that occurred in the Anchorage area. Three main agents of deposition were involved: glacier ice, flowing water in streams and on deltas, and still water in small lakes and ponds or in the ancestral Cook Inlet. Other deposits resulted from downward movement of loose material on slopes, and from wind. In general the deposits from the glacier ice are in two belts, one along the Chugach Mountain front and another in the northern part of the map area (including the Elmendorf Moraine). Stream and delta deposits dominate the area between these two belts as well as the hummocky region between Point Woronzof and Point Campbell. The deposits of ancestral Cook Inlet chiefly

underlie the broad low trough. Pond and lake deposits are scattered throughout the Anchorage area.

Local site conditions may consist of alluvium in abandoned stream channels and in terraces along modern streams. Gravel and sand appears to be generally well bedded and well sorted. Deposits in large channels and in other broad areas are chiefly gravel and are thicker than deposits in small narrow channels and terraces, which contain chiefly sand and gravel; some channels and broad areas may contain significant amounts of peat, silt or clay.

#### 2.1.3 Hydrology, Hydrogeology, Climatology

Freeze/thaw actions are the dominant physical processes affecting surface water hydrology, groundwater movement. and geomorphological weathering in the coastal sub-arctic region. Permafrost has been noted in the Anchorage area, but it is unknown if permafrost conditions exist on site.

Active soil layers have been found to range from 12 to 60 inches below the ground surface. Both compaction and excavation of soils will significantly alter the depth of the active layer. Local site soil conditions are unknown until lithology studies are conducted on site.

Local groundwater resources are unknown. There are no known current uses of local groundwater. Potable water for the site is available from the Municipality of Anchorage.

The mean average annual precipitation for Anchorage is 20 inches, the greatest quantity occurring in July and August. The mean average annual snowfall for Anchorage is 70 inches, with the peak occurring in late October or early December. The warmest and coldest months for the year are July (mean of 76°F.) and January (mean of 4°F., respectively). The ground surface temperature is usually below freezing by early November, remaining frozen until mid May. Breakup occurs in late March to late April.

### 2.1.4 Natural History

Numerous birds migrate through the area but none are reported to be endangered (Fish and Game). Black bears, moose foxes and small animals are native to the Anchorage area, but do not impact this site.

The vegetation of the Anchorage area is alpine which is dominated by herbs, grasses and sedges. Lowland areas consist of wetland grasses with lakes, bogs and generally poorly drained soils. Urban development, a lack of soils and harsh climate make plant populations and densities low.

#### 2.2.2 SITE BACKGROUND

Activity regarding Block 26-A of the East Anchorage Township has been recorded with the Anchorage District Recorder Office since 1940. Prior to 1940

land use was unknown. The current owner is The Fourth Ave Gambell, an Alaska Limited Partnership. Current land use is as a parking lot.

## 2.2.3 PREVIOUS INVESTIGATIONS

No known environmental assessments have occurred to date on Block 26-A.

#### 2.2.4 DATA USAGE

This environmental assessment will be used to determine site characteristics and to identify potential areas of contamination for Phase II activities.

#### . 3.0 DATA RECORDS

#### 3.1 DATA SOURCES EVALUATED

Data sources for this environmental assessment included a review of public records, maps, and other studies concerning this property. The following list identifies the data sources:

#### 3.2 PUBLIC RECORD REVIEW

EPA CERCLIS (Superfund) - Site Event Listing	(11/27/92)
EPA RCRA - Activity List for Region 10	(10/13/92)
ADEC - List of Contaminated Sites	(11/20/92)
ADEC - List of Leaking Underground Storage Tanks	(12/29/92)
ADEC - Hazardous Substances Spill Log - Last date as of	(12/28/92)
Municipality of Anchorage Tax Records	(08/21/92)
Alaska State Archives - Z.J. Lousaac Public Library	(08/08/92)
Anchorage Fire Department	(12/20/92)

#### 3.3 MAPS

U.S. Geological Survey Topographic Map, Anchorage Quadrangle, 1979 Anchorage Planning Commission, Geological, Soils, Map, 1991

#### 3.4 AERIAL PHOTOGRAPHS

Aeromap U.S. Inc., Aerial photograph dated 06/27/75, Scale 1"= 250'

### 3.5 OTHER DATA SOURCES

Real Estate Reference Maps Personal communications

#### 4.0 REGULATORY AGENCY LISTINGS

#### 4.1 CERCLA - CERCLIS

The U.S. EPA Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) indicates the presence of twenty-three (23) sites in the Anchorage area. Sixteen (16) of the sites appear to be located greater than two miles from Block 26-A and seven (7) sites appear to be within two (2) miles of the Block 26-A. Of the seven (7) sites within two miles of Block 26-A, six of the sites are located near the Port of Anchorage or near the Ship Creek area. These six sites are located north of Block 26-A at elevations that are approximately six (6) meters below elevation of Block 26-A. The seventh site is located on East 15th Avenue. The sites listed are:

AKD980978902	ALASKA AUTO CARRIERS	1600 SHIP AVE	ANC 99501
AKD980983241	ALASKA RAILROAD - ANCHORAGE YARD	OCEAN DOCK RD	ANC 99501
AKD980978787	STANDARD STEEL & METALS	2400 RAILROAD AVE	ANC 99501
AK5971522185	USDOD - DLA DEFENSE FUEL DEPOT	1217 ANC PORT ROAD	ANC 99501
AK4690600149	,	932 WHITNEY ROAD	ANC 99501
AKD084611219	CROWLEY ENVIRONMENTAL SERVICES	111 W. ROY ROAD	ANC 99503
AKD037995404	ALASKA ELECTROPLATING	828 E 15TH	ANC 99501

Listing on CERCLIS may only indicate a potential for environmental contamination, based on state and/or federal investigations, or a site previously investigated that requires no further action.

#### 4.2 RCRA

The Environmental Protection Agency (EPA) Resource Conservation and Recovery Act (RCRA) list shows the following businesses immediately adjacent to Block 26-A which generate or transport reportable quantities of hazardous materials.

#### Large Quantity Generators

AKD980975205	ANCHORAGE COMMUNITY COLLEGE	2811 MERRILL FIELD DR	ANC 99501
AKD037995404	ALASKA RAILROAD	411 W IST AVE	ANC 99501
AKD980981419	BOWEN TOOLS INC	4111 INGRA	ANC 99503
AKD983068602	NORTHWEST ENVIROSERVICE INC	1813 E 1ST AVE	ANC 99501
AKD055503825	TEXACO USA A DIVISION OF TEXACO INC	1601 TIDEWATER RD	ANC 99501
AK5750361086	USDHEW PHS ALASKA NATIVE MEDICAL CTR	255 GAMBELL	ANC 99501
AKD981769854	PAINT & SIGN SHOP	IST & POST RD BLDG 942	ANC 99501
AKD000831750	CHEVRON USA INC ANCHORAGE TERMINAL	CCEAN DOCK RD	ANC 99501

Large Quantity Generators which produce more than one thousand (1000) kilograms of listed wastes per month.

#### Small Quantity Generators

AKD035403708	ANCHORAGE CHRYSLER DODGE INC	2501 E 5TH AVE	ANC 99501
AKD039269618	ANCHORAGE MUNICIPAL LIGHT & POWER	1200 E 1ST ST	ANC 99501
AKD037995404	ALASKA ELECTROPLATING BUMPER REPAIR	828 E 15TH	ANC 99501
AKD983073768	ARCO ALASKA INC BAYVIEW	WAREHOUSE AVE	ANC 99501
AKD983074212	BATTERY SPECIALIST OF AK DBA UNITED	1939 E 5TH AVE	ANC 99501
AKD085191898	BIG OS AUTOMOTIVE	2401 E 4TH AVE	ANC 99501
AKD983073818	BOBS SVC INC	2009 SPAR AVE	ANC 99501

AKD980738405	EASTERN ELECTRIC APP REP CO	568 E WHITNEY RO	ANC 99501
AKD980987499	MAPCO ANCHORAGE ASPHALT STORAGE	900 OCEAN DOCK RD	ANC 99501
AKD983073271	REO 4009	310 E 1ST AVE	ANC 99501
AKD091748925	STEPP BROS LINCOLN MERCURY MERKUR	730 E 5TH AVE	ANC 99501
AK5971522185	USDOD DLA DEFENSE FUEL SUPPORT	1217 ANCH PORT RD	ANC 99502 >

Conditionally Exempt Small Quantity Generators produce less than one-hundred (100) kilograms of listed wastes each month.

#### RCRA Action Listed as Other

AKD980978985	VANGUARD TRANSPORTATION	800 WAREHOUSE AVE	ANC 99501
AKD982654527	ARCTIC TUG &BARGE CO INC	1200 OCEAN DOCK RD	ANC 99501
AKD130597818	BELUGA TRUCKING INC	1430 A ST STE 3	ANC 99501.
	BIG STATE MOTOR FREIGHT INC	300 GULL AVE	ANC 99501
AK0052764578	CARLILE ENTERPRISES INC	1524 SHIP AVE	ANC 99501
AKD122081243	GOLD STREAK FREIGHT LINES INC	1040 E 1ST AVE	ANC 99501
AKD980837308		1000 WHITNEY RD	ANC 99501
AKD018550228	M V CONSTRUCTOR CO PICKWORTH & ASSOC NORTHERN MARINE IN		ANC 99501
AKD103351532		1048 WHITNEY RD	ANC 99501
AKD070056239	MAMMOTH OF ALASKA INC	229 WHITNEY RD	ANC 99501
AKD980329868	THERMAL RECYCLING LTD	עש איחווויבן אט	WAC 33201

RCRA Action Listed as Other includes hazardous waste transporters, treatment, storage, disposal facilities (TSDFs) and Burn and Blend facilities.

## 4.3 ADEC - OIL AND HAZARDOUS SUBSTANCE LISTING

The Alaska Department of Environmental Conservation Oil and Hazardous Substances Listing (1992) identifies 90 sites adjacent to Block 26-A which are State of Alaska potential or confirmed sites. One site is listed NPL (CERCLA Superfund - See page 28, Number 336) and it should not impact Block 26-A. The sites are listed in Appendix B.

## 4.4 ADEC - HAZARDOUS SUBSTANCES SPILL LOG

The ADEC Hazardous Substances Spill Log was consulted to see if any recent incidents not covered under the ADEC Oil and Hazardous Substance Listing were listed. No spills were noted that would adversely impact Block 26-A.

#### 5.0 SITE HISTORY.

The site history is based on data obtained during this site assessment and from Sections 3.0 and 4.0. Dates are approximated where no explicit information is available. The chronology is from the oldest to the most recent. Information was derived from Municipality of Anchorage District Recorder Office files and the Alaska collection of Z.J. Loussac Public Library.

#### Previous to 1940

Prior Land Use Records Not Located

July 17, 1940

Property Owner: Thomas Peterkin

City of Anchorage Subdivision of Blocks No. 25 and 26, East Addition. Block 26-A consists of Lots 1 thru 6 facing third Avenue and lots 7, 8, 9, 10, 11 and 12

which are the subject of this report.
Status Plat Information: File page C-18

1940's

<u>Patterns of the Past - An Inventory of Anchorage's Historic Resources.</u> Editors Michael Carberry and Donna Lane, pg 37 "House Moved 1944 when Northern Commercial expanded operations on 4th and 5th Avenue."

#### January 13, 1941

Seller:

Thomas Peterkin

Buyer:

Seth B. Cook

Purchase:

Lot 8 Block 26-A of the East Addition to the Townsite of

Anchorage, Alaska

File:

Book and Page Number Unknown, Anchorage District Recorder

#### September 30, 1941

Seller:

Thomas Peterkin

Buver:

Chris Poulsen and Bert Schock

Purchase:

Lots 10. 11 and 12 of Block 26-A of the East Addition to the

Townsite of Anchorage, Alaska

File:

Book 32, Page 151, Anchorage District Recorder

#### October 04, 1943

Seller:

Seth B. Cook and Edna M. Cook

Buver:

Stefania Ulrich

Purchase:

Lot 8 Block 26-A of the East Addition to the Townsite of

Anchorage, Alaska

File:

Book and Page Number Unknown, Anchorage District Recorder

#### October 22, 1943

Seller:

Chris Poulsen and Bert Schock

Buyer:

Ken Hinchey

Purchase:

Lots 10, 11 and 12 of Block 26-A of the East Addition to the

Townsite of Anchorage, Alaska

File:

Book 32, Page 72, Anchorage District Recorder

#### July 28, 1944

Seller:

Ken Hinchey and Nadine Hinchey

Buyer:

Donald J. Peterson

Purchase:

Lot 10 of Block 26-A of the East Addition to the Townsite of

Anchorage, Alaska

File:

Book 27, Page 32, Anchorage District Recorder

#### March 13, 1947

Sellers:

Donald J. Peterson and Helen E. Peterson

Buyers:

Fred Wagar and Mary Rattray

Purchase:

Lot 10 of Block 26-A of the East Addition to the Townsite of

Anchorage, Alaska

File:

Book 58, Page 294, Anchorage District Recorder

#### September 25, 1947

Sellers:

Fred J. Wagar and Mary J. Rattray Northern Commercial Company

Buyer: Purchase:

Lots 10, 11 and 12 of Block 26-A of the East Addition to the

Townsite of Anchorage, Alaska

File:

Book 65, Page 326, Anchorage District Recorder

#### May 1957

Owner:

Stefanja Ulrich - Mrs R.E. Anderson executor of the lease

Lease:

E.F. Craig President of Peacock Cleaners.

Convey:

Lease of Lots 7, 8 and 9 of Block 26-A. Lots 7 and 8 later

combined into one lot known as Lot 8A.

File:

Book 246, Page 217, Anchorage Recording District

Lease Number 70333.

#### April 24, 1963

Deed of Trust:

Lots 7, 8, and 9 of Block 26-A

By:

Stefanja H. Anderson - Mrs. R.E. Anderson

Deed With:

Matanuska Valley Bank.

File:

Book 65, Page 353, Anchorage Recording District

#### May 26, 1964

Owner:

Stefanja Anderson executor of the lease

Lease:

Lloyd C. Conners and Frank A. Klith and C&K Sanitary Cleaners

Convey:

Lease of Lots 7 and 8 of Block 26-A.

File:

Book 86, Page 50, Anchorage Recording District

Unknown Lease Number

#### July 30, 1964

Survey:

Plat details Block 26-A and the location of a building located on

Lot 8A.

File:

Page No. 136-87, Anchorage Recording District

#### July 07, 1971

Grantor:

Stefanja Anderson a/k/a Stefanja Ulrich, deceased

Grantee:

Northern Commercial Company

Conveyed:

Lot 8A of Block 26-A

File:

File:

Book 432, Page 301, Anchorage Recording District

#### May 24, 1979

Deed of Trust

The Fourth Avenue Gambell, an Alaska Limited Partnership

Beneficiary:

Northern Commercial Company, a Delaware Corporation

Parcel 1 consists of Lots 8A of Block 26A of the East Addition to the

Townsite of Anchorage, Plat Number 64-100.

Parcel 2 consists of Lots 10, 11 and 12 of Block 26A of the East Addition

to the Townsite of Anchorage. Plat Number C-18. Book 405, Page 709, Anchorage Recording District

#### Present Land Use:

The site is currently used as a vehicle parking lot.

#### 6.0 DISCUSSION

Based on the above findings EnviroAmerica, Inc. offers the following:

- Prior to 1940, the land use of Block 26-A and Lots 8A, 9,10,11 and 12 is unknown. Recorded property documents indicate that the property was owned by Northern Commercial, Inc. and was used for various business enterprises until 1978. Plot plan records show a structure located on Lot 8A that was leased as a dry cleaning establishment. This structure is not in the site aerial photographs taken in 1976 and the date or the reason for its removal is unknown. However, the aerial photographs taken in 1976 do show three buildings on the northeast corner and east side of the property on what appears to be lots 10, 11 and 12. In 1978 these buildings were razed for unknown reasons. Interview data and a site visit indicates that these three buildings were utilized as a tire shop prior to their demolition. The current property was purchased by The Fourth Avenue Gambell in 1978 and is currently being utilized as a parking lot without attached structures.
- Adjacent land uses include business, residential housing and commercial and retail operations that are within one-tenth (.1) mile of the subject site. None of the businesses located immediately adjacent to Block 26-A are listed as generators of hazardous materials.
- At least eight (8) businesses within the immediate vicinity of Block 26-A store, use, or sell some quantities of hazardous substances as part of business activities. Twelve (12) businesses within the immediate vicinity of Block 26-A each generate less than one-hundred (100) kg per month of regulated waste and are classified as Conditional Small Quantity Generators. Ten (10) other businesses in the immediate vicinity of Block 26-A are listed by EPA as either transporters, TSDFs, or Burn and Blend facilities.
- Waste generation rates and types for this site is unknown. Record searches and resulting business activities indicate that this site may contain wastes generated from past dry cleaning operations, heating fuel use, tire shop activities and a parking lot. Specific site contaminates may include waste petroleum fuel, hydraulic fluid, glycol antifreeze, oil lubricants, chlorinated and non-chlorinated solvents, leaded gasoline byproducts, pesticides and PCB containing fluids if ballasts were buried on site during building demolition. Soil samples will be required to classify any wastes located on Block 26-A.
- Two site visits were conducted at this site. The visits occurred on November 28, 1992 and January 02, 1993. Items noted during both visits include:

Lot 8A - There is no evidence of the structure visible on site. No underground heating tanks, sewer lines, foundations or basement structures are visible.

Ground slope for the site appears to peak in the northern part of Lot 9. From this point all sheet runoff appears to run north, south, east and west. The greatest slope runs west from Lot 9 towards Gambell and results in an elevation difference of approximately two feet.

Foundations are apparent on Lots 10, 11 and 12 and these correspond to the three buildings in the 1976 aerial photographs. Lot 11 appears to contain a hydraulic hoist casing that is covered with a steel manhole cover.

One underground storage tank vent pipe is evident in the north section of Lot 12, approximately eight feet due south of the alley and adjacent to an existing power pole. The size, past uses or present contents of this tank are unknown.

• The surface topography slopes away from the site so that potential waste migration from adjacent ADEC, CERCLA or RCRA sites is low. Block 26-A slopes to the west and the east and south exposures to the site are protected by naturally occurring swales and the north is protected by a steep elevation gradient decrease to Ship Creek.

Based on the above conclusions, EnviroAmerica, Inc. is of the opinion that the potential for hazardous substances existing in the environment of the site from past uses is medium. The risk to the environment can be mitigated provided that approved waste management practices are immediately implemented to remove all existing or suspected underground storage tanks on site.

Other contaminants that may be on site are unknown. Phase II tank removal sampling activities should be expanded beyond Gasoline or Diesel range hydrocarbons and include analysis for organics, chlorinated solvents, PCBs/Pesticides and Metals.

All corresponding wastes should also be disposed of in accordance with all applicable State of Alaska and Federal hazardous waste disposal regulations. The use and disposal of waste materials in accordance with applicable regulations should not present a risk to the environment, however such cannot be assured.

#### 7.0 CLOSURE

The findings we have presented within this report are based on limited research conducted at this site and should not be construed as a definite statement regarding reported conditions. No subsurface explorations, soil testing, or sampling of building materials was conducted at this site in reaching our conclusions.

The data presented in this report should be considered representative of the time of our site observations. Changes in the conditions of the property can occur with passage of time, whether they be due to natural processes or to human actions on this or adjacent properties. In addition, changes in Government Codes, regulations, or laws may occur. Due to such changes, our observations and recommendations applicable to this site may need to be revised wholly or in part, due to changes beyond our control.

EnviroAmerica, Inc. conducted this environmental assessment within our best judgement to adequately describe the known and anticipated conditions of the property. This report was prepared for the exclusive use of The Fourth Avenue Gambell and their representatives in the study of Block 26-A in Anchorage, Alaska and in no way guarantees that any agency or its staff will reach the same conclusions as EnviroAmerica, Inc.

## Attachment (A)

# Data Sources

The Fourth Avenue Gambell Environmental Assessment

#### Reference Materials

- U.S. Environmental Protection Agency. August 1988. Guidance for Conducting Remedial Investigations and Feasibility Studies Under CERCLA, Interim Final.
- U.S. Environmental Protection Agency. June 1988. Community Relations in Superfund, A Handbook, Interim Version.
- OSWER Directive 9230.0-3B. Office of Emergency and Remedial Response, Office of Solid Waste and Emergency Response, U.S. EPA, Washington, D.C.
- U.S. Environmental Protection Agency. December 1987. A Compendium of Superfund Field Operations Methods. OSWER Directive 9335.0-14. Office of Emergency and Remedial Response, Office of Solid Waste and Emergency Response, U.S. EPA, Washington, D.C.
- U.S. Environmental Protection Agency. August 8, 1988. CERCLA Compliance with Other Laws Manual. OSWER Directive 9234.1-01. Office of Emergency and Remedial Response, Office of Solid Waste and Emergency Response, U.S. EPA, Washington, D.C.
- U.S. Environmental Protection Agency. March 1987. Data Quality Objectives for Remedial Response Activities. OSWER Directive 9355.0-7B. Office of Emergency and Remedial Response, Office of Solid Waste and Emergency Response, U.S. EPA, Washington, D.C.
- U.S. Environmental Protection Agency. October 1986. Superfund Public Health Evaluation Manual. OSWER Directive 9285.4-1. Office of Emergency and Remedial Response, Office of Solid Waste and Emergency Response, U.S. EPA, Washington, D.C.
- U.S. Environmental Protection Agency. October 1985. Remedial Action at Waste Disposal Sites Handbook (Revised). EPA/625/6-85/006. U.S. EPA, Office of Emergency and Remedial Response, Washington, D.C.
- NIOSH OSHA USCG EPA. October 1985. Occupational Safety and Health Guidance Manual for Hazardous Waste Site Activities.
- Flint, R.F., 1971, Glacial and Quaternary geology: New York, John Wiley and Sons, 892 pp.
- Miller, R. D. and Dobrovolny, Ernest, 1989, Surficial geology of Anchorage and vicinity, Alaska: U.S. Geol. Survey Bull. 1093, 128 pp.
- Schmoll, H. R., Dobrovolny, Ernest, and Zenone, Chester, 1971, Generalized geologic map of the Eagle River— Birchwood area. Greater Anchorage Area Borough, Alaska: U.S. Geol. Survey open-file map.

# Attachment (B)

# State of Alaska List of Contaminated Sites

The Fourth Avenue Gambell Environmental Assessment

50 92210027302 NAPA Auto Supply 2605 E. 5th Ave.

Anchorage 99501 1,000 gallon gasoline & 500 gallon diesel tanks removed. Contaminated soil removed and stockpiled on-site.

92210027502 52 Stepp Brothers Lincoln Mercury

Anchorage 99501 Pulled 7,500 gallon gasoline and two 1,000 gallon waste oil tanks.

Contamination found at each of the waste oil tanks.

58 91210910001 Quality Transmission 1208 Gambell Street

Anchorage 99501

Polychlorinated biphenyl & waste oil contaminated soil in ground & in 30 cu. yds. of excavated soil from removal of 5,000 gallon underground tank. Reported 4/10/91. Petroleum products have stained ground around site. Low level PCB and TPH remain in Tank #1 excavation. Vertical and horizontal extent of contamination unknown. Human health threat unknown. Second UST to be removed.

60 91210016901 Arctic Speedy Glass 901 E. 5th Ave.

Anchorage 99501

Underground storage tanks at site. Preliminary site assessment revealed soil contamination, extent of contamination & impact to human health is unknown.

91210022801 AK Import Auto Center 839 E. 8th Ave.

Anchorage 99501

Gasoline soil contamination discovered when tanks pulled in 8/91.

Contamination found at tanks, piping elbow & pump island. Soils stockpiled on site.

62 88210014602 B & L 4th Ave. Service

556 E. 4th Ave.

Anchorage 99501

Waste oil contaminated soils found during 5/88 UST removal. Contaminated soils removed and land farmed (treatment) on-site. ADEC requires no further site assessment or remediation. Date and amount of original spill unknown. Low public health threat.

88210034201

Former Firestone Auto Service

333 W. 7th Ave.

Anchorage 99501

Soil waste oil contamination found during 11/88 waste oil UST removal. Contaminated soils excavated. Date and quantity of original spill unknown. The real extent of contamination remaining is less than 10,000 sq. ft. Low human health threat.

70 89210122902
AK Vehicle Accessories
4651 Gambell St. Anchorage 99503
Surficial waste oil contaminated soils documented 11/89. Traces of halogenated solvents. Soils have been excavated. ADEC has not required further soil remediation or site assessment.

77 89210124302
Chevron Bulk Plant
Port of Anchorage Anchorage 99501
Petroleum contamination & chlorinated solvents present at site. Impact to human health unknown. Date of release unknown.

78 89210113801
Tesoro Bulk Plant
1522 Anchorage Port Rd.
Port of Anchorage Diesel fuel leak in pipeline on 5/18/89 contaminated surface soils. Historic spillage at the site entered sewerline adjacent to bulk plant.
Quantities and extent of contamination significant. Potential health concern for workers. Contaminated soils excavated and long term remediation facilities installed in 1990.

84 91210017802
Ak Sales and Service Truck Center Anchorage 99501
Elevated hydrocarbons found in waste oil excavation in small amounts.
Confirmation samples confirmed presence of "clean" soil beneath system. Total extent of contamination to be documented at later date with closure report.

85 90210027101
AK Sales & Service Inc.
1300 E. 5th Ave.
Anchorage 99501
During removal of 1500 waste oil tank soil contamination was found. 24 year old tank with gas, oil, solvents and sludge. Facility ID
0-001-952. Unknown human health impact.

88 89210025101
AK Sales & Service Inc.
1246 E. 5th Ave.
Anchorage 99501
Diesel & gasoline contamination of soil has been found in ongoing underground storage tank removals. Human health impact unknown.

91 89210011701
Anchorage Chrysler Dodge
2601 E. 5th Ave.
Anchorage 99501
Soil contaminated by waste oil/gasoline documented at UST facility in 5/89.
Groundwater contamination by chlorinated solvents/gasoline constituents documented 6/89. Date and quantity of spill unknown. USTs and contaminated soils removed 1989. Real extent of contamination remaining estimated 10,000 square feet. Potable groundwater supplies at risk.

#### 104 91210122805

Pool Arctic Anchorage 99501 Petroleum contamination found on AK railroad Leased land contract #5536. Floor sump drain runs to 55 gallon drums under slab. Total extent & type of contamination & impact to human health is unknown.

#### 106 91210020002 Yukon Equipment, Inc.

2020 E. 3rd Ave. Anchorage 99501 Leaking underground waste oil storage tank. Soil contamination present, impact to groundwater unknown and impact to human health unknown.

#### 113 91210023102

Benson Trucking 4600 Gambell St.

Anchorage 99503 During underground storage tank removal contaminated soil excavated & stockpiled at site. Surface contamination was present before pull.

#### 117 91210010203

315 E. 2nd Ave.

Anchorage 99501 During removal of 1,500 gallon gasoline underground storage tank soil contamination identified. Impact to human health & total extent of contamination

#### 127 90210018402

Mat-Su. Inc.

unknown.

1705 Ship Ave.

Anchorage 99501 Leaking underground storage tank-diesel tank & waste oil tank with numerous surface spills. Soil contamination present & groundwater contamination possible.

#### 129 90210028201

Mammoth Alaska

1048 Whitney Rd.

Anchorage 99501 Removal of regulated waste oil, diesel, & gasoline tanks revealed soil & groundwater contamination present. Impact to human health, amount & extent of contamination unknown.

#### 130 91210033601

Chris Bera Inc.

1748 Post Rd.

unknown.

Anchorage 99501 Discovered petroleum contamination during underground storage tank removal. Type of contaminant, total extent of contamination, impact to human health is

19.

#### 148 91210910002 2346

Drum Site

2346 Railroad Ave.

Anchorage 99501

25-30 drums reported to contain hazardous material, waste, or substance. They have been there for a Long time & may rust out releasing contaminants to soil.

#### 150 92210018902

Snow White Cleaners

300 E. 5th Ave.

Anchorage 99501

Diesel contamination was found in vicinity of regulated underground storage tank.

#### 154 90210021404

City Electric Inc.

819 Orca St.

Anchorage 99501

Waste oil, gasoline, & diesel contamination from underground storage tank removal. Impact to human health, extent & amount of contamination unknown.

#### 156 84210925001

Ak Electroplating and Bumper

828 E. 15th Ave.

Anchorage 99503

Chemicals and metals used in electroplating discharged to municipal sewer system in form of tainted rinse & wash water. No further action needed-EPA.

#### 157 92210024501

Port of Anchorage-Admin Building

2000 Anchorage Port Road

Anchorage 99501

Diesel contamination discovered around fill/vent piping during removal of 12,000 gal. UST used for emergency generator fuel supply.

#### 163 90210006801

Craig Taylor Equipment Co.

733 E. Whitney Rd.

Anchorage 99501

Spill date unknown. All contamination removed during underground storage tank removal. Little to no human risk & no groundwater contamination.

#### 173 90210105301

Service America

1115 Whitney Rd

Anchorage 99501

Diesel contaminated soils encountered while removing 2 heating oil USTs. Approx. 75 cubic yards of contaminated soils removed. Trace of halogenated organics detected in north UST waste soils. Extent of residual contamination, human health threat, date and quantity of release unknown.

179 89210013701 Mapco Express #5009

1209 Gambell Street

Anchorage 99501
Gasoline/diesel soil contamination encountered in 9/87. Groundwater contamination documented 5/89. Trace trichloroethane and benzene above MCL detected in groundwater in 7/90. Potable groundwater supplies threatened. Six USTs removed in 5/89, and 338 tons of contaminated soil removed from site and processed in 6/89. Used oil contaminated soils are stored at Mapco #2 pending treatment. Real extent of contamination estimated at 10,000 sq. ft.

181 90210028803 Willow Park Housing 9th Ave. & Fairbanks S

9th Ave. & Fairbanks St.

Anchorage 99501
Soil & groundwater contamination present in removal of S underground storage tanks. 2 tanks are gasoline-500 gallons each, 1 heating oil-750 gallons, 2 with bunker C at 7000 gallons each.

186 87210031602 Unocal #4581 636 C Street

Anchorage 99501
Soil/groundwater gasoline contamination documented in 10/86 during station demolition. At least 200 cubic yards contaminated soils removed. in-place soil contamination remediation by vapor extraction. Date and quantity of original spill unknown. Real extent of contamination remaining estimated less than 10,000 square feet. Human health threat unknown.

187 86210020603 Unocal #4652

Anchorage 99501 600 gallon gasoline leak from UST facility contaminated soil/groundwater in 1986. Contaminated soils and USTs removed in 1987 Real extent of remaining contamination estimated at 10,000 square feet. Soil vapor extraction treatment of in place soils. Groundwater treatment by air stripping. Human health threat unknown.

189 88210023201

Former Texaco
1006 W. 5th Ave.
Anchorage 99501
Gasoline/diesel/waste oil with PCB contaminated soils found during 8/88 UST removal program. Majority of site contamination removed by 7/89.
Contaminants detected in shallow, on-site groundwater. Date and quantity of

original spill unknown. Unknown human health threat.

89210011604 190 Consolidated Freightways

801 W. 1st Ave. Anchorage 99501 Contaminated soils/groundwater encountered during 1989 removal of USTs and subsequent site assessment. Contaminants include gasoline and diesel. Approximately 700 cubic yards contaminated soil and 1000 gallon contaminated water removed. Extent of contamination unknown. Date & quantity of spill unknown. Human health threat unknown.

90210033801

Denali Fuel Co.

Anchorage 99501 1525 E. 5lh Ave. Gasoline, diesel fuel and heating oil tanks removed excavated approx. 380 cubic yards of soil. Stockpiled soil on site. Impact to human health unknown.

89210027602 Aurora North Fuel Sales Anchorage 99501 1040 E. 1st Ave. Extensive oily layer over ground of yard & around fuel dispensing island. Assessment not yet made. Extent of contamination & human health impact remains unknown at this time.

88210011901 195 Defense Fuels Center Anchorage 99501 Port of Anchorage Underground tanks leaking, documented fuel surfacing on the hillside below buried 100,000 gallon fuel tank. The fuel has contaminated the shallow groundwater and a small creek nearby. Dates of release, quantity, extent of contamination, and health impact unknown.

9021001310Z 214 4th & Ingra Anchorage 99501 901 4th Ave. Contaminated soil from gas/diesel fuel. Amount & extent of contamination, impact to human health unknown

89210024901 215 Mapco Express #5010 Anchorage 99501 1500 E. 5th Gasoline/diesel soil contamination documented 9/87. Groundwater contamination documented 1/90. Floating product (gasoline) has moved off site. Approx. 100 cubic yards contaminated soils removed during upgrading facility in 1989. Vapor extraction system began operation in 4/90 to treat contaminated soils remaining in place. Date and quantity of original spill unknown. Contamination threatens potable groundwater resources.

220 92210027604

C.R. Lewis Company

1500 Post Road

Anchorage 99501

Waste oil and gasoline tank removed. Some contaminated soil removed and stockpiled on-site. Unknown if waste oil is a LUST.

225 92210007604

Anchorage Native Hospital

255 Gambell Anchorage 99501 It appears that overfilling of gasoline USTs has resulted in soil contamination.

226 88210014601

Former Providence Hospital

9th & L, West side of L

Anchorage 99501

Bunker C contaminated soils found during tank removal. Contamination limited to excavation. File closed no further action required.

231 91210909201

Preservative Paint Co.

245 Post Rd.

Anchorage 99501

Paint Co's warehouse had burned down with worst case scenario of chemical contamination: muriatic acid, zinc dust, lead chromate, silica, solvents(methyl ethyl ketone, toluene, acetone, xylene). Total extent, amount & type of contamination is unknown.

232 91210116901

Industrial Lots Railroad Ave.

1730 & 1820 Railroad Ave.

Anchorage 99501

Lead & petroleum contaminants found in groundwater from a possible leaking underground storage tank. Type & extent of contamination, impact to human health unknown.

233 91Z10129001

Diesel Storage Tank Pump House Anchorage 99501
The seal of the diesel engine loading pump failed. 600 gallons of diesel fuel were spilled, sorbants were laid down and 100 gallons were recovered.
Approximately 750 sq. ft. of soil contaminated.

241 91210008001

Westours Bus Maintenance Facility

1850 E. 1st Ave.

Anchorage 99501

12,000 gallon leaking underground storage diesel tank. Soil contamination present, unknown impact to groundwater and human health.

251 82210922501

Standard Steel & Metals Co.

2400 Railroad Ave.

Anchorage 99501

CERCLA PCB contaminated soils, petroleum wastes, metals, dioxin & other hazardous waste encountered at this facility during 1986. wastes secured on site as well as removed from site under EPA direction. Dates, duration & quantity spillage unknown. Extent of remaining contamination unknown. Human health risk mitigated by EPA actions.

253 89210129901

Weaver Brothers

1611 E. 1st Ave.

Anchorage 99501

Spilled diesel on the lot from a drum was contained, but so far hasn't been disposed of or a report filed. Contamination probably contained no probable impact to human health. No further action required, file closed.

256 90210132302

Sig World Transfer & Storage

2824 Rampart Dr.

Anchorage 99501

Waste oil, grease, & hydraulic fluid used in vehicle maintenance at site. Waste oil was spilled. Impact to human health unknown.

258 90210014303

Northern Consolidators

1907 Post Rd.

Anchorage 99501

Contaminated soils found at site. Amount & extent of contamination & impact to human health unknown.

259 89210013602

Arrow Moving & Storage

209 W. Post Rd.

Anchorage 99501

Diesel contaminated soil was replaced in the ground. Groundwater was not assessed during the leaking underground storage tank removal. Extent of contamination and human health impact remains unknown.

260 89210013604 Air Van Lines/North America 2216 Post Rd.

Anchorage 99501 Grade diesel contaminated soils were replaced in ground & groundwater were not assessed during leaking underground storage tank removal of 1,030 gallon tank. Full extent of contamination & human health impact unknown.

265 92210013902

ARCO Towers Office Building

700 G. Street Anchorage 99501 Diesel contaminated soil found upon removal of underground storage tanks.

272 89210013603

GCI Warehouse

135 W. Post Rd. Anchorage 99501 Diesel contaminated soils were replace in ground & groundwater was not assessed during leaking underground storage tank removals. Extent of contamination & human health impact unknown at this time.

92210904904

Municipal Light & Power, Plant 1

821 E. 1st Ave.

Anchorage 99501 During 1964 earthquake, 100,000 gallons of diesel oil were released at the site by a collapsing storage tank. Soils were contaminated with diesel fuel. Subsequent releases occurred on the site including PCBs from electrical equipment. Chlorinated solvents in the groundwater has not been confirmed.

90210012002

Hobbs Industries Power Plant

229 Whitney Rd.

Anchorage 99501

R.Godden found visual/olfactory evidence of the presence of significant amounts of petroleum contaminated soil during underground storage tank removal. Impact to human health and extent of contamination unknown.

90210108601

Suburban Propane Sales-Rampart

3107 Rampart Dr.

Anchorage 99501

Faulty nozzle on diesel above ground storage tank has resulted in several spills this winter. One was estimated at 300 gallons.

281 90210026303 AWWU Pump Station #2

12th Ave. & O St.

Report of a petroleum release from underground diesel fuel tanks or piping. Impact to human health unknown. Soil contamination level & extent unknown.

284 89210107402
AK Railroad Anchorage Yard
Winter use of unknown quantity of oil/ethylene glycol mix on switches. Human health impact & extent of contamination unknown. Citizen complaint has been filed with ADEC.

285 85210134501
Ship Creek Railroad Yard
Suspected dumping of waste oil on river bank of Ship Creek located approximately 100 feet upstream of C Street Bridge at Ship Creek. Impact to human health unknown.

291 89210131101
Residence 11th Ave.
1333 W. 11th Ave.
Home heating fuel underground storage tank w/contaminated soil(near vent valve) a 261 ppm & 80.6 ppm total petroleum hydrocarbons probably related to overfills. Date of occurrence & impact to human health unknown. File closed, no further action anticipated.

Unocal #5580
442 Gambell Street
Anchorage 99501
Soil/groundwater gasoline contamination identified in 11/86 site investigation.
Quantity and date of original spill unknown. The extent of contamination is not accurately known. No known private wells in site's area of impact. Low human health risk.

EnviroAmerica, Inc. Phase 1 - Visual Site Inspection Data Collection F	Page 12 of 17
	ection Not Applicable
Enter the following into Watershed Description  a) Segment Name (i.e., River,  b) Segment Type (i.e., Sm-Lg-Med Pond, La	on Lake) ake, or River)
Segment	Туре
Ship Cucele Sur. Stream	W. of Site 1.5mi
Attach a simplified sketch of surface water runoff:	AttachedX_N/A
Likelihood of Release:	
Does quantitative or qualitative evidence exist to i water contamination?HighModeratex	indicate site-related surface
Describe: Sheet ranoff to storm doa	un system.
Close Water Containment:	<u> </u>
Surface Flood Water Containment:	110 0T 100 m T
Determine flooding frequency where this source year) year.	is located: (10 - 25 - 100 or 50
N/A	
MIZ	
	<u> </u>

THE PARTY AND

1

	oAmeric_, Inc.	Page 13 of 17
		Section Not Applicable
NI	In PlaceNone	
N N N	umber of Monitoring Wells?  umber Upgradient?  umber Downgradient?  umber of Abandoned Wells?  umber of Damaged Wells?	
G	roundwater Monitoring Schedule6 mo	
	Available R	
Well #	Location	Condition
		·
Notes:		
<del></del>		
\		

Phase I - visual Site inspection Data Col	ilection Form
Air Migration Pathways>	Section Not Applicable
Does quantitative or qualitative evidence excontaminate releases to air?High	xist to indicate site-related _ModerateLow
Describe: (Daily event)	
Determine the distance from the emission stresidence, regularly occupied building or a	
Estimate the population to the site emission	n source:
Estimated Popu	
Offsite (miles) 0-1/4 1/4-1/2 1/2-1	
1-2 2-3 3-4	
Determine the distance from the emission types of land uses:	source and each of the following
Land Use	Distance (miles)
Commercial Single Family Residential Multi-Family Residential Parks Prime Agricultural	
Non-prime Agricultural Notes:	
Determine the distance from the emission environmentally sensitive area within 2 m	n source to each potentially niles:
Area	
	·

Page 14 of 17

EnviroAmeric , Inc.	Page 15ol 17
Phase 1 - Visual Site Inspection Data Collection Form	
Offsite Contamination Section !	Vot Applicable
Does quantitative or qualitative evidence exist to indicate si contamination on the property of a park, school, playground designated for use by the public?HighModerate_	OF melana ana
Notes:	
Residential housing is the mile fire as is a Church o Hospital Site contains we unlikely to impact local over	parking lot. area. our site (NA) minant Site muse
since 1940	
	· · · · · · · · · · · · · · · · · · ·
· · · · · · · · · · · · · · · · · · ·	

EnviroAmeric\_, Inc. Page 16 of 17 Phase 1 - Visual Site Inspection Data Collection Form Site Sketch (Show North, all pertinent features, sources and targets) Garbell Noture traspural Hyder Bates 211

SC 000050

EnviroAmerica, Inc.

Page 17 of 17

Phase 1 - Visual Site Inspection Data Collection Form

Surface Water Sketch

(Show North, runoff route, probable point of entry, fisheries, intakes and targets)

(						
			Ship C	مر م جر		
					1	
11.000	6 mater	clearati	ow			
U369 -		HOSP				
			1.	.5 т. арр	ron	
	60	26 a		-		
To Julet	15		uth			
					Post Rd	+
·				50	uale	
	<del>                                    </del>					
	The state of the s			Not to	scale	-
	swole		No	targe	lt Ell van	
			010 60	L duair d H2O U	ell vane 14. Juk,	

308 90210021403 N & S Texaco Station

901 E. 15th Ave.

Anchorage 99501 Removal & upgrade of underground storage tanks revealed soil contamination. Impact to human health, extent & amount of contamination unknown.

88210023601 309

Jack's Market 8th Ave. & I St.

Anchorage 99501 Petroleum contaminated soils found during tank removal. Soil & groundwater contamination appears to be restricted to site. Quantity released, extent of contamination unknown. No public health threat identified to date. No further action required at this time, file closed.

314 87210034305

Unocal #5031 566 E. Bluff Rd.

Anchorage 99501 11/86 site assessment documented soil/groundwater contaminated by petroleum hydrocarbons. Petroleum UST facility on-site. Real extent of contamination estimated at less than 10,000 square feet. Spill date, duration and public health threat unknown.

318 89Z10034602 Waldron Company 1005 East 6th Avenue Anchorage 99501 Gasoline/diesel/waste oil contaminated soils encountered during the removal of numerous USTs. Approx. 200 cubic yards contaminated soils removed. Date, quantity of spill and extent of contamination unknown. Public health threat unknown.

324 89210018201 Texaco Service Station 901 C St. Anchorage 99501 Underground storage tank removals showed hydrocarbon and benzene. toluene, ethylbenzene, xylenes contaminating the soil.

325 90Z10018405 Chevron #2555 920 Gambell St. Anchorage 99501 Leaking underground storage tank removal with extent & level of contamination unknown.

330 90210103601

Five Finc.

5th Ave. & G St.

Heating oil tank 500 gallon tank capacity contaminated soils found during underground storage tank removal. Amount, extent human risk unknown.

331 89210025502

Eastchester Texaco

1035 Gambell Street

Anchorage 99501

Petroleum contaminated soil found during tank removal. Impact to human health unknown. Extent & amount of contamination unknown.

336 88210925701 Arctic Cooperage CERCLA

932 Whitney Rd.

Anchorage 99501

Alleged hazardous dumpsite from oil refining sludge and barrel reconditioning operation during 1970's and early 80's. Site may contain PCB s, dioxins, solvents, sulfuric acid and other unknown chemicals. 100 by 100 area with visible contamination. Quantities released, dates, extent of contamination, & health impact unknown.

337 90210120401

Texaco USA

1601 Tidewater Rd.

Anchorage 99501

6000 gallon underground storage tank removed with soil contaminated from leaks, spills, overfills. Impact to human health unknown.

339 86210119902

Submarine Pirelli Cable #10

Knik Arm

Anchorage 99501

A submarine electrical transmission line for three years has been slowly leaking a dielectric fluid called dodecylbenzene into Cook Inlet. The total amount leaked & the extent of contamination is unknown. There are no specific public health concerns. No further action required file closed.

340 88210102601

Chevron Tank Farm

Port of Anchorage 99501

Site investigation in December 1987 identified soil & groundwater contamination from petroleum bulk plant facility. Amount and date(s) of release, extent of contamination and health impact unknown. Possible floating product on groundwater in 6 monitoring wells in < 710,000 square foot area.

344 90210001101

AK Center for the Performing Arts

621 W. 6th Ave.

Anchorage 99501

40 gallons of #2 diesel discharge to city sewer on 01/11/92. No other known impacts. Underground storage tank under construction with an integrity investigation.

346 89210015001 B & B Tool Supply Inc.

1100 E. rd Ave.

Diesel contamination with some degree of polychlorinated biphenyls at old underground storage tank site. Total extent of contamination off-site & human health impact unknown at this time.

health impact unknown at this time.

347 91210007001
Government Hill 7-11
751 E. Loop Rd.
Anchorage 99501
Removal of 6 regulated underground storage tanks: (1) 6,000 gal. unleaded gas, 2 4,000 gal leaded gas, 2 4,000 gal Leaded super. (1) 500 gallon used oil tank revealed soil contamination.

Captain Cook Travel
743 W. 5th Ave.

Gasoline, diesel and waste oil release from UST system. Surface spillage, approx. 10 cubic feet soils affected, reported April 18, 1991. Three USTs removed in May 1991. 100 to 1,000 cubic feet of diesel, gasoline and waste oil contaminated soils remain in place. Lead contaminated soils, about 100 sq. feet, detected. Approx. 150 cubic yards of soils excavated. Human health threat unknown.

351 91210124601
Columbus Distributing
1849 E, 1st Ave.
Anchorage 99501
A 1,000 gallon regulated waste oil tank containing diesel leaked and contaminated 15 cubic yards of soil.

354 90210018401
Wrightway Auto Carriers
101 W. Whitney Rd.
Underground storage tank vent and fill pipe on regular gasoline tank has soil contamination around them. Diesel dispenser has surface spills all around it. Impact to human health unknown and extent unknown.

355 90210026701
AK Sight Seeing Tours
349 Wrangell St.
Anchorage 99501
Removal of 5,000 diesel, (2) 5,000 gasoline, & (1) 500 gallon waste oil underground storage tanks revealed soil contamination. Extent & amount of contamination unknown. Impact to human health unknown.

356 90210001102 Municipal Light & Power 1201 E. 3rd Ave.

1201 E. 3rd Ave.

UST removal in 11/89 detected soils contaminated by gasoline and diesel. No soil/groundwater assessment has been done to determine the extent of contamination. Human health risk has not been determined.

357 89210021401

Municipal Light & Power

1120 East 1st Avenue

Anchorage 99501

Soil/groundwater contaminated by gasoline/diesel and waste oil constituents (PCE) found during 7/89 site assessment. USTs and contaminated soils removed 10/89. Real extent of remaining contamination estimated at 100 square feet. Date and quantity of original spill unknown. Human health threat unknown.

358 89210008601
ML&P maintenance Facility
1021 East 1st Avenue
Anchorage 99501
Unleaded gasoline contaminated soils/groundwater documented during 4/89
UST removal. Approx. 400 cu. yds. of contaminated soils removed. Remediation of contaminated soils in place by vapor extraction began 1/90. Groundwater treatment by pumping & air stripping began 1/90. Waste oil pit contained halogenated organics. Spilled gasoline estimated S00-1100 gal. Date of spill unknown. Extent of gasoline, but not waste oil, contamination known.

361 87210919201
AK Auto Carriers
1600 Ship Ave.
Anchorage 99501
Alleged buried materials consisting of 15 5 gallon containers of water based non-lead paint, (8) 25# bags of sheetrock spackle, several bags of drywall texture, a crane tower/boom, various wood split beams. EPA: No further action needed. Site closed out.

363 90210917301

AMFAC warehouse
250 Post Rd.

Anchorage 99501

Diesel contaminated soils encountered during 5/90 underground storage tank removal. Polychlorinated biphenyl contamination discovered during Site assessment in 8/90 at a waste oil disposal system. Partial remediation occurred in 1990. Date and quantity of spill unknown. Area of extent of Site contamination estimated under 10,000 sq. ft. Public health threat to transients camping in the immediate area.

365 89210027604 AK Railroad Yard 445 Warehouse Ave.

Anchorage 99501

Diesel contaminated soil encountered during removal of an UST in 9/89. Contaminated soils removed. Extent of contamination and human health threat unknown.

367 90210131901

Warehouse

3237 Mtn. View Dr.

Anchorage 99501

Site investigation shows surface spills & tanks not removed. Transformers are present which may contain polychlorinated biphenols. PCB's are in lighting fixtures asbestos in building & roofing materials. Level & extent of contaminant unknown.

371 92210109402

Automatic Welding & Supply

3038 Rampart

Anchorage 99501

In response to a citizen complaint, discharges of oily waste to storm drain was discovered.

373 91210125601

Wilburs

4025 W. South

Anchorage 99501

A diesel fuel release was reported on 09/13/91. The volume of release is

unknown. A 100 yards strip of grass was impacted by the spill.

## Attachment (C)

## **EA Data Collection Form**

The Fourth Avenue Gambell Environmental Assessment

	Americ , Inc.	a Collec		age 1 of 17
Phase 1 - Visual Site Inspection Data C Client List			Section Not	Applicable
	Aerial Photos Site Drawings Photographic Survey  Swledge of Potential Problem  Potential Contaminate Asbestos Drums Contaminated Soi Contaminated H20 Air Contamination X Lead Batteries Transformers PCB's Ballasts X UST's AST's Ground Water Wes X Solvents Monitoring Wells Medical Waste Radiation Source Explosives Confined Spaces Unknown Other	ns that nts il	Site Type Landfill Waste Pile Surface In Buildings Containers Incinerator Pads Tank Store Fire Pits Land Trea River - Po Injection V Ground W Survey To I Single Fa Multiple F Office Cor Undevelo Commerce X Commerce	npoundment s r age atment nd - Stream Wells fater Wells include: mily amily mplex ped Lot sial Building
Qty i	ltem	Unit	Location	Contaminants
City	None Known			}
	IVU PARA DE SANTA DE			
		ļ		
		<del> </del>	<del> </del>	<del> </del>
		<del>                                     </del>	<del> </del>	
		•		
		+		1

EnviroAmerica, Inc. Page 2 of 17
Phase 1 - Visual Site Inspection Data Collection Form
General Information
Site Number- Androgage Townsite  USGS/TWP/Range Legal Description Slock 26A - Lets 8A 9, 10, 11, 12
Site Description
Site Name Block 26A
Site Address  Address Conner 4th Ave a Gambell St  City/Borough/State Huchorage Ak Zip 99501
Site Operator (s)
Name The Fourth Are Gambell, Address 1343 6. St City/State Prolonage, Ak 99501
Site Owner
Name The Fourth Are Gambell Address 1343 G 5 t City/State Auchorage At Phone (902) 274-2634
Dates of Ownership from to Present
Type of Ownership: ResidentialBoroughCommercialFederalStateState
Notes:  Lot bondered by Lots 1-6 Block ZGA  to Not site - Hyder St. to East-Gambell  St to West and 4th Ave to South.

	Page 3 of 17
nase 1 - Visual Site Inspection Data C revious Owner(s)	Officeron 1 ann
Name <u>See Report.</u> Address for husbrucal. City/State	- Chas 5 dala
Phone ( —)	<del></del>
Dates of Ownership Type of from 1229 to free Present owner	OwnershipResidentialCommercialStateBoroughMunicipalOther
	· · · · · · · · · · · · · · · · · · ·
<u>.</u>	
Data Source: XSite Visit XReco	ords Search_ ClientInterview
Data Source: Site Visit X Reco	ords Search_x_ClientInterview
Data Source: XSite Visit XReco	ords Search_xClientInterview
Data Source: XSite Visit XReco	ords Search_x_ClientInterview
Data Source: *Site Visit *Recorderty Uses: Parking Lot	ords Search_x_ClientInterview
roperty Uses: Pasking Lot	
roperty Uses: Pasking Lot	ords Search_x_ClientInterview  / Activities
roperty Uses: Pasking Lot  Regulator	
roperty Uses: Pasking Lot	

Work

EPA Generator ID #

EnviroAmeri _ 1, Inc. Phase 1 - Visual Site Inspection Dat	a Collection For	Page 4 of 17
		<del></del>
JST's - AST's	_ Section	Not Applicable
Past evidence of UST's on Site?	_X_Yes	No
_X_Vent Pipes		
Above ground Pipir	ng -	·
Fill pipes—— Ø		
Partially buried US		
Evidence of Soil or	Water staining	·
Evidence of hazard		
No evidence of haz	ardous waste m	nigration
Estimate of number of UST's or	n site	
GPR data	<del></del>	
Magnetic Survey		
Fill pipe count		•
Vent pipe count		
Christy Box Count		
Cistern Pipe Count		
Notes:		
One vent pipe noted -	Wol Lo-	+ 12-8H So of
alley - West to pole.	Client Ind	licates other tank
may be prejent on site		-
i	ered with	steel cover
In Lot 11 approximately	= 3015 of	sley - See skotel
Number of AST's on Site <u>PIA</u>	<del></del>	
Do tanks appear to	have product?	(v/n)
Are tanks labeled?		(7)
Tanks intact		
Tanks damaged	•	,
Drain ports evident		
Soil or Water stain	ing .	
No evidence of ha		
Evidence of hazard	dous waste migi	ration?
From tank?		
From assoc	iated piping?	•
Dikes in place and	in good repair?	?
Dikes damaged?	-	
No dikes on site?		
Adequate dike free	eboard? (y/n)	
Notes:		•

	roAmeric	-		Data (	Collection f		Page 5 of 17
)rum	S		•	X,	Sectio	n Not A	Applicable
	No Evid	ence o	f Drum:	s on Si	le	_Drums Of	fsite
	Drums on SRandomPalletizInside BPressur	n Distri ed Building		- - -	Evide	sed to Wea	ied drums
	Location	City	Cond	Туре	Volume	DOT	Remarks
						·	
<del></del>							
			i				
			1				
	Condition		Ť	ура	······································	Estimated	Volume
(RI) (RE) (FS) (L) (B) (PL) (PE) (X)	Rusted Full Rusted Empty Factory Seal Leaking Burst Punctured-Proc Punctured-Emp		(17E) (17H) (S/S) (P) (SO)	Bung Open Stainle Poly Steel (	oss Overpac	(F) Full (7) 75% (5) 50% (2) 25% (P) < 1° (E) Emp	1
(F) Fi	Compressed Gas	Combustib	ole (I) lg Reactive	nitable (W) Wat	(COR) Corros er Reactive	tive (R) Rad (OX) Oxidizer	lioactive (P) Poison (E) Explosive

EnviroAmerica Phase 1 - Visual Sit	•		Data C	ollection f	-orm	Page 6 of 17
CB's (TSCA)	0 11101	-				Applicable
robable PCB contain	ning a	articles (	on site:			
Transformers X_BallastsSwitch Gear		Pa	luipmer ads oles	nt Racks		Carrier Fluid (TCE) Dielectric Fluid
Location	Qty	Cond	Type	MUC	DOT	Remarks
Lot 8A	Unk		_			Buried with building on vernoved
						on socal all.
						Peacock of WC Building
Gardillon.		T	/De		Fetti	nated Concentration
Condition  (RI) Rusted Full  (RE) Rusted Empty  (FS) Factory Seal  (L) Leaking  (B) Burst  (PL) Punctured-Product  (PE) Punctured-Empty  (X) Other		(B1) (B2) (54) (60) (P) (SW) (PD) (F)	Ballast < Ballast > Ballast > Equipme Dielectron Poles Switch G	9 lb int Racks : Fluid	CSIII	(1) < 50 ppm (2) > 50 ppm (5) > 500 ppm (U) Unknown (E) Empty
Notes:	-					
DOT Classifications  (F) Hammable (C) Con (CG) Compressed Gas	bustible RE) R	le (!) lgr	ntable ( (W) Wate	COR) Corros	ive (R) R (OX) Oxidiz	adioactive (P) Poison er (E) Explosive

Phase 1 - Visual Site Inspection Data Collection Form  andfill (RCRA) Section Not Applicable  andfill (RCRA) Section Not Applicable  andfill Status: Interim Permitted Part B SWMU CERCLA Part A applied for Part B SWMU CERCLA Waste debris exposed - Uncontrolled waste pile Waste totally contained in intact structure or containment Waste migration evident Waste migration not evident TSDF  Cover: Impermeable material Vegetation None Engineered Staining of soil cover Waste uncovered or exposed Soil/cover thickness?  Cover soil resistant to gas migration? High Moderate Low  Liner: Functioning Non-Functioning None Number of Liners?  Gas Collection System: Functioning Non-Functioning None Leachate Collection: Functioning Non-Functioning None Security System: Functioning Non-Functioning None Consite Documentation: Functioning Non-Functioning None Qurly Records Maintenance  Monitoring Wells: Functioning Non-Functioning None Number of Wells? Upgradient? Downgradient? Downgradient? Downgradient?  Applicable Subparts:  Medical Wastes Incinerators Drip Pads Silos Financials Recycling SPCC Plan Hazwoper Waste Piles Surface Impdmnts Subpart X  Other:	<b>Enviro</b>	America, li	nc.		Page 7 of 17
andfill Status:InterimPermittedPartial ClosurePart A applied forPart BSWMUCERCLAWaste debris exposed - Uncontrolled waste pileWaste totally contained in intact structure or containmentWaste migration evidentWaste migration not evidentTSDF	hase 1	- Visual Site Ins	pection Data (	Collection Form	
Part A applied forPart BSWMUCERCLAERCLA	andfill	(RCRA)		Section No	ot Applicable
Waste debris exposed - Uncontrolled waste pile    Waste totally contained in intact structure or containment    Waste intally contained in non-intact structure or containment	andfill St	F	art A applied f	Permitted orPart B	_Partial Closure SWMU
Impermeable materialVegetationNoneEngineeredStaining of soil coverWaste uncovered or exposedSoil/cover thickness?  Cover soil resistant to gas migration?HighNoderateLow  Liner:FunctioningNon-FunctioningNone		_Waste debris ofWaste totally ofWaste totally ofWaste migrationWaste migrationWaste migration	exposed - Unc contained in int contained in no on evident	act structure or con- in-intact structure	ontainment ,
Liner:FunctioningNon-FunctioningNone Number of Liners?	<u></u>	<u> </u>	Staining of soil Waste uncover	cover red or exposed	NoneEngineered
Number of Liners?   Gas Collection System:	Cover soi	il resistant to ga	s migration?_	HighMoc	ierateLow
Leachate Collection: Functioning Non-Functioning None  Security System: Functioning Non-Functioning None	<u>Liner:</u>	Function	oningNor Liners?	n-Functioning -	_None
FencingSignageGuard  Onsite Documentation: FunctioningNon-FunctioningNone	Gas Colle Leacnate	ection System: Collection:	Functio	ningNon-Fu ningNon-Fu	InctioningNone InctioningNone
Monitoring Wells:  Functioning Non-Functioning None Number of Wells? Upgradient? Downgradient?  Medical Wastes Incinerators Drip Pads Silos Financials Recycling SPCC Plan Hazwoper Waste Piles Containers Surface Impdmnts Subpart X Tanks Land Treatment	Security	System:	Function	oningNon-Fu FencingSi	unctioningNone gnageGuard
Number of Wells? Upgradient? Downgradient?  Applicable Subparts:  Medical WastesIncineratorsDrip PadsSilosFinancialsRecyclingSPCC PlanHazwoperWaste PilesContainersSurface ImpdmntsSubpart XTanksLand Treatment	Onsite D	ocumentation:	Function	oningNon-Fu	unctioningNone Maintenance
Medical Wastes Incinerators Drip Pads Silos Financials Recycling SPCC Plan Hazwoper Waste Piles Containers Surface Impdmnts Subpart X Tanks Land Treatment	Monitorir	<u>na Wells:</u>	Num Upgr	per of Wells? adient?	
Silos Financials Recycling SPCC Plan Hazwoper Waste Piles Containers Surface Impdmnts Subpart X Tanks Land Treatment	Applicat	ole Subparts:			
	Other:	Silos SPCC Plan Containers		_Financials _Hazwoper _Surface Impdmn	Recycling Waste Piles Subpart X
				· · · · · · · · · · · · · · · · · · ·	

200

EnviroAmeric ., Inc.	Page 8 of 17
Phase 1 - Visual Site Inspection Data Colle	
Waste Piles X S	ection Not Applicable
Containments	
Fire Pits	Not Applicable
Fire Pit Status: Active Inactive	·
Fire Pit Type: Above Ground	Below Ground Soil/Cover Thickness?
Describe:	
Soil resistant to gas migration? High	ModerateLow
Waste Piles (RCRA) Containers Type - (Pile - Cistern - Building - Tank, etc.)	Not Applicable
Describe:	
Dimensions:	
Constructed of:	
Waste Pile	Container
Waste File	Container
Intact, Sealed	_Open or non-intact
Unsealed	_Rustea through
Factory Seal Cover Ripped	_Liner Ripped Punctured
Cover Maintained	r directored Burst
Liner Maintained	Partially Buried
Uncovered	Intact
No Liner	Contents:
Runoff Controls	Evident None
	Solid Liquid
Structures	Not Applicable
RCRA Closed	Hazardous migration
No Hazardous Waste Evident	Waste Piles Pad Only
Tank(s) on site	Drains - Outfalls

:ЛVIГОАГ	neric., Inc. Page 9 of 17 Visual Site Inspection Data Collection Form
urface In	npoundmentX_ Section Not Applicable
lurface Impo	undment - (Diked- If dry evaluate as a landfill)
nclosure:	EnclosedNon-enclosedNone
Cover::	Totally CoveredPartial CoverMaintainedMaintainedNot Maintained
	Engineered cover in place and in good repairNo coverDamaged CoverNot Secured
Vegetation:	HeavyLightSparceNone
Windbreak:	Site surrounded by windbreakNone
Hazmat:	Evidence of hazardous waste migration No evidence of hazardous waste migration
<u>Liner:</u>	Liner evident Number of Liners? No Liner
<u>Dikes:</u>	Dikes on site No dikes on site Adequate dike freeboard? (y/n)
	Water Staining? (y/n)Soil Staining? (y/n)Water Sheen? (y/n)
Notes:	

ection Form	
_ Section (	Not Applicable
ist to indicate si _HighMod	te-related erate <u>X</u> Low
on site	unknown. ater appears
he aquifer is Ka	rst:
	Karst (y/n)
aquifer litholog	y units:
Depth to	Depth to
Aquiter	Contamination
Aquiter	Contamination ———— ———
Aquiter	Contamination
Aquiter	Contamination
	nking water well:
the nearest dri	
the nearest dri	
the nearest dri	
	tist to indicate si  HighMod  The site  A ground which is Kan  The aquifer is Kan  The aquifer litholog  Depth to

Page 11 of 17

EnviroAmerica, Inc.
Phase 1 - Visual Site Inspection Data Collection Form
Probable Drinking Water

Wor	L Know	<b>n</b>				 
					·	
				<u> </u>	<del></del>	
			<del></del> -			 
		<del>.</del>			·	
table '	Water Use:					
	Used for	ommer	cial crop	S		
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage c Used fo Used fo Comme	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	s vestock wa ood prepar r than drin	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	
otes:	forage cUsed forUsed forCommeNot use	ommer r comm r comm rcial us d for a	cial crop nercial linercial fonces ness othe ny of the	es vestock wa bod prepar r than drin a above	atering ation king water	